




Installation in a glider hull

Determining the positions
using the drilling template



Pre-drill with a thin drill


Drill with a 7 mm drill bit





Deburring drill holes

Prepare self-adhesive silver foile




Place the LED board and apply 2K adhesive (e.g. epoxy) to the corners



LED boards glued on the inside, protected against dirt on the outside with clear adhesive film





With the aid of the silver foil, the elements can be securely positioned and no dust can penetrate from any side

After wiring and connecting to the electronics, you should avoid looking into the extremely bright light when testing!

Have fun installing it – and flying.

